

DAIMLERCHRYSLER

EMISSIONS RECALL G30 **REPLACE THE OXYGEN SENSOR MODULE AND REPROGRAM THE ECM**

Dear: (Name)

Chrysler LLC has determined that some **2007 and 2008 model year Dodge Ram 2500/3500 trucks** equipped with a 6.7L diesel engine may not comply with Federal and California emissions regulations.

The problem is... **The On-Board Diagnostic (OBD) system on your truck (VIN: xxxxxxxxxxxxxxxxxxx) may not detect a failed oxygen sensor or illuminate the Malfunction Indicator Light as required. In addition, the OBD system may cause your truck to fail an Inspection Maintenance (Readiness) test and may not store mileage as required for certain transmission faults.**

What your dealer will do... **Chrysler will repair your vehicle free of charge (parts and labor). To do this, your dealer will replace the Oxygen Sensor Module and reprogram your truck's Engine Control Module. The new software will also improve vehicle driveability and reduce the potential for exhaust soot accumulation in your vehicle's particulate filter. The work will take about 1 hour to complete. However, additional time may be necessary depending on service schedules.**

What you must do... Simply **contact your dealer** right away to schedule a service appointment. Ask the dealer to hold the part for your vehicle or to order it before your appointment.

If you need help... If you have questions or concerns which your dealer is unable to resolve, please contact Chrysler at 1-800-853-1403.

California residents... **The State of California requires the completion of emission recall repairs prior to vehicle registration renewal.** Your dealer will provide you with a Vehicle Emission Recall Proof of Correction Form after the recall service is performed. Be sure to save this form since the California Department of Motor Vehicles may require that you supply it as proof that the recall has been performed.

Please help us update our records, by filling out the attached prepaid postcard, if any of the conditions listed on the card apply to you or your vehicle.

If you have already experienced this condition and have paid to have it repaired, you may send your original receipts and/or other adequate proof of payment to the following address for reimbursement: Chrysler, P.O. Box 4639 Oak Ridge, TN 37831, Attention: Reimbursement.

In order to ensure your full protection under the emission warranty provisions, it is recommended that you have your vehicle serviced as soon as possible. Failure to do so could legally be determined to be a lack of proper maintenance of your vehicle. Further, without this repair, your vehicle may fail a state or local emission inspection test.

We are sorry for any inconvenience but trust that you understand our interest in clean air. Thank you for your attention to this important matter.

*Buckle up
for Safety!*

Customer Services Field Operations
Chrysler LLC
Notification Code G30