



**EMISSIONS RECALL J35
REPROGRAM ECM – REGENERATION STRATEGY**

Dear: (Name)

Chrysler has determined that some **2007 through 2009 model year Dodge Ram 2500/3500 trucks equipped with a 6.7L diesel engine** may require reprogramming of the Engine Control Module (ECM).

The problem is... The ECM software program on your truck (VIN: xxxxxxxxxxxxxxxxx) may cause illumination of the Malfunction Indicator Light (MIL) when no problem exists or under certain conditions allow heavy sooting of the turbocharger, exhaust gas recirculation valve and diesel particulate filter. Heavy sooting could damage emissions components and result in increased emissions.

What your dealer will do... **Chrysler will repair your vehicle free of charge (parts and labor).** To do this, your dealer will reprogram your vehicle's ECM. **The new software will eliminate false illumination of the MIL and reduce the potential for exhaust soot accumulation in your engine and emissions components.** The work will take about ½ hour to complete. However, additional time may be necessary depending on service schedules.

What you must do... Simply **contact your dealer** right away to schedule a service appointment.

If you need help... If you have questions or concerns which your dealer is unable to resolve, please contact Chrysler at 1-800-853-1403.

California residents... **The State of California requires the completion of emission recall repairs prior to vehicle registration renewal.** Your dealer will provide you with a Vehicle Emission Recall Proof of Correction Form after the recall service is performed. Be sure to save this form since the California Department of Motor Vehicles may require that you supply it as proof that the recall has been performed.

Please help us update our records by filling out the attached prepaid postcard, if any of the conditions listed on the card apply to you or your vehicle. You may also update this information on the web at
CCCCCCCCCCCCCCCCCCCCCCCCCCCC

If you have already experienced this condition and have paid to have it repaired, you may send your original receipts and/or other adequate proof of payment to the following address for reimbursement: Chrysler Recall Customer Assistance, P.O. Box 21-8007, Auburn Hills, MI 48321-8007, Attention: Reimbursement.

In order to ensure your full protection under the emission warranty provisions, it is recommended that you have your vehicle serviced as soon as possible. Failure to do so could legally be determined to be a lack of proper maintenance of your vehicle. Further, without this repair, your vehicle may fail a state or local emission inspection test.

We are sorry for any inconvenience but trust that you understand our interest in clean air. Thank you for your attention to this important matter.

Customer Services Field Operations
Chrysler Group LLC
Notification Code J35