DaimlerChrysler



CUSTOMER SATISFACTION NOTIFICATION F19 - ROLL-OVER VALVE VENT HOSES

Dear: (Name)

Customer satisfaction is very important to DaimlerChrysler. Accordingly, we are recommending the following service on some 2006 model year Dodge Ram 2500 and 3500 pick up trucks equipped with a Cummins Diesel engine.

allow water to enter into the fuel tank. Excessive water in the fuel can damage the injection pump and/or injectors if the engine is off for an

extended period of time.

What your dealer will do...

 ${\bf Daimler Chrysler\ will\ repair\ your\ vehicle\ free\ of\ charge\ (parts\ and\ labor).}$

To do this, your dealer will install a hose on each roll-over valve and if necessary remove any water in found in the fuel and install a new fuel filter. The work will take about 1 hour to complete. However, additional time may be necessary depending on how dealer appointments are scheduled and

processed.

What you must

do...

Simply **contact your dealer** right away to schedule a service appointment. Ask the dealer to hold the parts for your vehicle or to order them before your

appointment. Remember to bring this letter with you to your dealer.

If you need help...

If you have questions or concerns which your dealer is unable to resolve, please

contact DaimlerChrysler at 1-800-853-1403.

Please help us update our records, by filling out the enclosed prepaid postcard, if any of the conditions listed on the card apply to you or your vehicle. Be sure to print the last eight (8) characters of the VIN (VVVVVVV) and notification code F19 on the postcard.

If you have already experienced this condition and have paid to have it repaired, you may send your original receipts and/or other adequate proof of payment to the following address for reimbursement: DaimlerChrysler P.O. Box 4639 Oak Ridge, TN 37831, Attention: Reimbursement.

We're sorry for any inconvenience, but we believe that this service will help to ensure your continuing satisfaction with your vehicle. Thank you for your attention to this important matter.

Customer Services Field Operations DaimlerChrysler Corporation Notification Code F19